



DOUBLE DIGITAL CALIPER MICROTECH

USER MANUAL



Calibration ISO 17025:2017

ISO 9001
BUREAU VERITAS
Certification



ISO 9001:2015

Item No	Range		Resolution	Accuracy	Jaws	Waterproof	Display
	mm	inch			External		
141111155	0-200	0-8"	0,005	±60	150	IP54	Digit height 9mm

BUTTON FUNCTIONS

Switch between metric and English measurement systems

ON/OFF function



ORIGIN function after battery change (Press 5 sec)

Switching between absolute and relative measurement (display INC) or setting ZERO

FUNCTIONS

IP54 ELECTRONICS
HAND FINISHED SURFACES
CR1632 3V BATTERY

MM/INCH
POSITION MEMORIZED
AUTO WAKE UP & SWITCH OFF

OPERATION INSTRUCTIONS

Wipe with a clean cloth, soaked in gasoline, measuring surface of the frame and gauge calipers to remove anti-corrosion oil. Then wipe them with a clean dry cloth.

If necessary, open the battery cover; insert the battery (type **CR1632**) according to the polarity of the electrodes. Blinking display information or absence suggests replacing battery.

It will be indication on display «-----» after battery chnging. Press **ORIGIN** button for 5 sec to start reading system.

During the measurement avoid warps of measuring surfaces of the instrument. Measuring surface must be fully in contact with the measurement object.

After finishing work wipe the measuring surfaces of the caliper with a cloth soaked in gasoline and apply anticorrosion oil.



WARNING!

IN THE PROCESS OF WORKING WITH CALIPERS SHOULD BE AVOIDED:

Scratches on the measuring surfaces;

Measuring the size of object in the process of machining;

Shocks or dropping, avoid bending of rod or other surfaces.

